

Bid No. 2022-159 Annual Contract for Purchase of Self-Propelled Road Brooms

	Primary Award		Secondary Award		Alternate Award			
* Item does not meet specifications.	TUSCO dba Underwood Equipment Company Fort Worth, TX		Closner Equipment Rhome, TX		R. B. Everett and Company Haltom City, TX		Associated Supply Company, Inc. Euless, TX	
	HUB:	No	HUB:	No	HUB:	No	HUB:	No
	COOP	Yes	COOP	Yes	COOP	Yes	COOP	Yes
Description	Unit Price		Unit Price		Unit Price		Unit Price	
Item 1: Self-Propelled Road Broom with a Center Broom								
Price of Equipment per Specification	\$68,589.00		\$74,000.00		\$76,917.00		**\$92,200	
Brand/Model of Equipment Bid:	Superior Broom DT74J		Rosco RB50		Broce RJT350		Laymor SM450ST	
Estimated Delivery Time After Receipt of Order:	24 Weeks		12 Months		28 Weeks		6 Months	
Standard Manufacturer Warranty:	1 Year/ 1,000 Hours On Machine 5 Year/ 3,000 Hour On Engine		2 Year Standard Warranty		1 Year - Broce Broom - 5 Year Warranty Provided by John Deere		1 Year	
Item 2: Self-Propelled Road Broom with a Front Mounted Broom								
Price of Equipment per Specification	\$72,127.00		\$83,000.00		*\$105,944		No Bid	
Brand/Model of Equipment Bid:	Superior Broom SM74J		Rosco NV55		Broce FMJ470		No Bid	
Estimated Delivery Time After Receipt of Order:	24 Weeks		12 Months		12 Weeks		No Bid	
Standard Manufacturer Warranty:	1 Year/ 1,000 Hours On Machine 5 Year/ 3,000 Hour On Engine		2 Year Standard Warranty		1 Year - Broce Broom - 5 Year Warranty Provided by John Deere		No Bid	
Optional Pricing:								

Extended Warranty	<b>\$7,160.00</b> <b>Premier - 60 Months 3,000</b> <b>Total Hours</b>	<i>\$4,669.50</i> <i>60 Months or 5000 Hours</i>	No Bid	No Bid
Discount off List for Items Not Listed: .	<b>15%</b>	12%	0%	No Bid

ROMCO Equipment Company LLC and Ergon Asphalt & Emulsions, Inc. submitted a no bid.

\*R. B. Everett and Company does not meet specifications for item two because the inside turning radius exceeded the maximum allowable turn radius of 72 inches, all wheels are not interchangeable from front to rear axles, inner diameter of tube exceeded the maximum allowable diameter of 7 feet 6 inches and does not have a defroster as required.

\*\*Associated Supply Company, Inc. did not meet specifications for item one because they failed to bid an audible engine alarm, minimum 95 amp engine and did not bid a parking brake with a buzzer.